

Disbondment along overlap of a spirally wound tape coating and a holiday at one section

8

Fig. 1(c)




Fig. 2





Fig. 3

Tapered channel 0.375" wide 0.120" deep max 0.040" deep min









Fig. 4(a)

Fig. 4(b)





Test 1 polarization and pH data collected under a coating disbondment and adjacent exposed defect.



defect and under an adjacent coating disbondment.